

# LEASE FACILITY INSPECTION REPORT

DNR/Office of Conservation

SRCN9960

<b>Serial Num</b> 251809	<b>Date</b> May 19, 2020	<b>Operator</b> Southwind Oil & Gas Llc	<b>Id</b> S5683
<b>Lease Name</b> AUS C RA SU80;CROWELL LM 30 H # 002		<b>Address</b> 5555 San Felipe Street, Suite 3556	
<b>Section:</b> 030 <b>Township:</b> 01S <b>Range:</b> 01W		Houston , TX 77056-	
<b>Parish</b> RAPIDES			
<b>Field</b> Masters Creek <b>Id:</b> 6565		<b>Contact</b> Toni Kelley	

## A. INSPECTION REASON

## REVISION

**Request by District Office**

**Complaint #:**

**Order #:**

## B. WELL SITE

1. **IDENTIFICATION:** Passed

2. **CONDITION:** Passed

**Transportation to Site:** TRUCK

## C. TANK BATTERY

1. **IDENTIFICATION:** Passed

2. **CONTAINMENT:** Passed

**Type:**

3. **BLEEDERS** **Exist:** N/A **Passed**

4. **PIPELINE SALES VALVES:** Passed

**Transporter:**

5. **B S & W VALVES:** Passed

6. **MECHANICAL ARRANGEMENT:** Passed

7. **STRUCTURAL INTEGRITY OF STORAGE TANKS:** Passed

8. **VENTING OF STORAGE TANKS** Passed

## D. FIRE HAZARD

Passed

## E. DISCHARGE OF E&P

Deficiency

**Violation(s):** E&P Waste Discharge

**Discharge Status:** Past

**Discharge Comments:** Cooler erupted at the well site during maintenance operations and discharged what appears to be less than 5 bbls of E&P waste ( mist of crude oil & SW ) to a wooded area behind the location.

## F. DISPOSITION OF E&P

**Site Id:**

**Site Name:**

## G. EXISTENT PITS:

No

**REMARKS:** STATE POLICE INCIDENT # 20-01698 PHONED TO HOT LINE 5-18-20. THE INCIDENT OCCURRED ON 5-17-20.  
MARATHON ON SITE PRODUCTION SUPERVISOR JEREMY MASCORRO, PHONE 361-254-0422.  
E-MAIL ojmascorro@marthonoil.com.  
Please issue C.O. ASAP so that they will have the guidance to move forward.  
Note: At this time the Operator has an operation underway to Temp. P&A this well. No work permits to approve this have been requested from the Monroe Office of Conservation.

# LEASE FACILITY INSPECTION REPORT

DNR/Office of Conservation

SRCN9960

THE OPERATOR'S REPRESENTATIVE SHALL SIGN THIS REPORT TO ACKNOWLEDGE RECEIPT OF HIS COPY, YOUR SIGNATURE CANNOT BE CONSTRUED AS AN ADMISSION OF GUILT FOR ANY VIOLATIONS CONTAINED IN THIS REPORT.

JEREMY MASCORRO  
Operator's Representative

May 19, 2020

**IN COMPLIANCE No**

**Sealed: N**

ROBBIE EDWARDS  
Conservation Enforcement Agent

May 19, 2020

Sonris Id: 760779

**Latitude (Deg/Min/Sec:) 30 56 53.4 Longitude (Deg/Min/Sec:) 92 30 55.5**



**Subject: destroyed cooler**

Photo File Name: F-1218382328/IMG\_0069.JPG



**Subject: impacted area**

Photo File Name: F-510533977/IMG\_0064.JPG



**Subject:** well

Photo File Name: F922937074/IMG\_0070.JPG